

## SERVICE BULLETIN AMATEUR RADIO

SUBJECT	DATE
TS-950SD N.B. GATE SWITCHING NOISE	01/11/90

Switching noise from the main band noise blanker circuit may be induced on the 15V line and pass through the AF amplifier to the speaker. The following modification will correct this condition.

NOTE: This modification has already been performed on models starting with serial number 104XXXX.


### REQUIRED PARTS:

120 OHM, 1/8 WATT RESISTOR                      PART # RD14BB2B121J  
100uF, 16V ELECTROLYTIC CAPACITOR              PART # CEO4EW1C101M

1. Disconnect the power cord and antenna.
2. Remove the top and bottom covers (18 screws).
3. Locate the AF board. This is the front left board of the 4 boards on the bottom of the transceiver.

THIS WORK WILL BE DONE ON THE COMPONENT SIDE OF THE AF BOARD.

1. Cut the foil as shown in the accompanying diagram.
2. Add a 120 ohm resistor between the emitter of Q48 and the 15V line.
3. Add a 100uF, 16V capacitor between the 15V line and ground.
4. Reassemble the transceiver.



This modification is covered under the 1 year warranty.  
Time required to perform the modification is 0.5 hrs. (C)011190EWP

KENWOOD U.S.A. CORPORATION

2201 EAST DOMINGUEZ STREET • LONG BEACH, CALIFORNIA 90810  
MAILING: P.O. BOX 22745 • LONG BEACH, CALIFORNIA 90801-5745  
TELEPHONE: (213) 639-9000